

A F F I D A V I D

STATE OF FLORIDA
COUNTY OF PALM BEACH

BEFORE ME THIS DAY PERSONALLY APPEARED T.D. BICKHAM OF THE FIRM OF ARTHUR V. STROCK & ASSOCIATES, INC., WHO BEING FIRST DULY SHORN DEPOSES AND SAYS;

That Plat errors were discovered In the plat of Pheasant Walk Section Two, as recorded In Plat Book 32, Page 111, of the Public Records of Palm Beach County, Florida, and that said errors are as follows:

1. The distance along the north line of Lot 25, Block 2 reads 50.80', but should read 51.44'.
2. The distance along the north line of Lot 31, Block 2 reads 103.13', but should read 102.49'.

A resurvey of the subdivision has been made within the last ten (10) days and reveals no evidence on the ground of way of conflict with the corrections as stated in this affidavit.

T.D. Bickham
REGISTERED LAND SURVEYOR NO. 1560
STATE OF FLORIDA

Sworn to and submitted before me this 15TH DAY OF August A.D. .1977

NOTARY PUBLIC
STATE OF FLORIDA AT LARGE